pREBOA-PRO™ Catheter
Quick Reference Guide

PRYTIME MEDICAL™
www.prytimemedical.com

Prime, pull vacuum, close



Attach and flush both ART lines entirely



Insert catheter and secure



Re-flush both ART lines entirely



Partial occlusion



pSBP: 90 - 110 mmHg
dSBP: >20 mmHg & pulsatile
- Zone 1: Up to 2 hours
- Zone 3: Clinical judgement

OR

Complete occlusion (only when neccessary)



dSBP: ≤20 mmHg or non-pulsatile
- Zone 1: Up to 30 min
- Zone 3: Up to 60 min

Re-flush both ART lines every 15 minutes



Pull strong vacuum with empty 30 mL syringe, evacuate syringe



Pull 2nd strong vacuum with empty 30 mL syringe, close stopcock, remove catheter



Remove sheath, manage access site, check for pulse in both legs



The pREBOA-PRO Catheter instructions for use (IFU) should be read in its entirety before using this device.
For more information and clinical references, visit https://prytimemedical.com/

Connect with our online learning system:
The REBOA Academy™

PRYTIME MEDICAL™
The REBOA Company™
www.prytimemedical.com
888.887.3262

7102-01 | Revision F